

Ergebnisse des Scannerdurchlaufs

| | Hyundai I20 (silber) | | Volvo XC40 (grau) | | BMW 3er (weiß) | | BMW 5er (blau) | |
|--------------------|----------------------|-----------|-------------------|-----------|----------------|-----------|----------------|-----------|
| | Anzahl | Ø | Anzahl | Ø | Anzahl | Ø | Anzahl | Ø |
| Motorhaube | 63 | 30 | 126 | 20 | 35 | 20 | 42 | 30 |
| Kotflügel VL | 15 | 30 | 12 | 20 | 6 | 20 | 8 | 20 |
| Kotflügel VR | 12 | 30 | 6 | 20 | 3 | 30 | 4 | 20 |
| Tür VL | 6 | 30 | 7 | 20 | 8 | 20 | 6 | 20 |
| Tür VR | 9 | 30 | 4 | 20 | 6 | 30 | 5 | 20 |
| Tür HL | 5 | 30 | 15 | 20 | 5 | 20 | 3 | 20 |
| Tür HR | 12 | 30 | 2 | 20 | 4 | 20 | 7 | 20 |
| Dach | 95 | 40 | 155 | 20 | 121 | 20 | 0 | 0 |
| Dachrahmen L | 19 | 30 | 13 | 20 | 25 | 30 | 23 | 20 |
| Dachrahmen R | 14 | 40 | 9 | 20 | 14 | 30 | 16 | 30 |
| Heckklappe Oben | 7 | 30 | 0 | 0 | 0 | 0 | 14 | 20 |
| Heckklappe Unten | 5 | 30 | 5 | 30 | 4 | 30 | 6 | 20 |
| Seitenwand HL | 16 | 30 | 18 | 20 | 11 | 20 | 1 | 30 |
| Seitenwand HR | 4 | 40 | 7 | 20 | 17 | 20 | 3 | 30 |
| Jury gesamt | 282 | 32 | 379 | 19 | 259 | 22 | 138 | 21 |
| Autoscan | 310 | 43 | 241 | 33 | 236 | 32 | 114 | 30 |
| ADI | 281 | 24 | 294 | 20 | 225 | 19 | 117 | 18 |
| HAST | 269 | 33 | 326 | 23 | 266 | 26 | 88 | 20 |
| Elscope Vision | 270 | 39 | 270 | 25 | 230 | 24 | 93 | 24 |

Detailergebnisse ADI



| | Hyundai I20 (silber) | | Volvo XC40 (grau) | | BMW 3er (weiß) | | BMW 5er (blau) | |
|--------------------|----------------------|----|-------------------|----|----------------|----|----------------|----|
| | Anzahl | Ø | Anzahl | Ø | Anzahl | Ø | Anzahl | Ø |
| Motorhaube | 81 | 40 | 75 | 30 | 19 | 30 | 39 | 30 |
| Kotflügel VL | 12 | 20 | 12 | 20 | 6 | 20 | 11 | 20 |
| Kotflügel VR | 12 | 20 | 7 | 20 | 4 | 20 | 5 | 20 |
| Tür VL | 6 | 30 | 8 | 20 | 9 | 20 | 7 | 20 |
| Tür VR | 12 | 30 | 4 | 20 | 8 | 20 | 3 | 20 |
| Tür HL | 4 | 30 | 9 | 20 | 4 | 20 | 4 | 20 |
| Tür HR | 14 | 30 | 3 | 30 | 5 | 20 | 8 | 20 |
| Dach | 93 | 30 | 134 | 20 | 123 | 30 | 10 | 20 |
| Dachrahmen L | 13 | 30 | 14 | 20 | 17 | 20 | 14 | 20 |
| Dachrahmen R | 16 | 30 | 7 | 30 | 12 | 30 | 10 | 20 |
| Heckklappe Oben | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Heckklappe Unten | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Seitenwand HL | 14 | 20 | 14 | 20 | 13 | 20 | 1 | 20 |
| Seitenwand HR | 4 | 20 | 7 | 30 | 5 | 20 | 5 | 20 |
| Dellensumme | 281 | | 294 | | 225 | | 117 | |

Detailergebnisse Autoscan



| | Hyundai I20 (silber) | | Volvo XC40 (grau) | | BMW 3er (weiß) | | BMW 5er (blau) | |
|--------------------|----------------------|----|-------------------|----|----------------|----|----------------|----|
| | Anzahl | Ø | Anzahl | Ø | Anzahl | Ø | Anzahl | Ø |
| Motorhaube | 72 | 40 | 79 | 30 | 24 | 20 | 33 | 30 |
| Kotflügel VL | 19 | 50 | 11 | 30 | 13 | 40 | 14 | 40 |
| Kotflügel VR | 24 | 40 | 5 | 30 | 9 | 40 | 11 | 30 |
| Tür VL | 8 | 70 | 3 | 40 | 12 | 40 | 7 | 40 |
| Tür VR | 12 | 60 | 2 | 20 | 6 | 40 | 4 | 30 |
| Tür HL | 0 | 0 | 7 | 50 | 1 | 20 | 4 | 30 |
| Tür HR | 0 | 0 | 3 | 30 | 3 | 20 | 6 | 40 |
| Dach | 126 | 60 | 106 | 50 | 116 | 40 | 4 | 10 |
| Dachrahmen L | 15 | 80 | 4 | 70 | 22 | 50 | 15 | 40 |
| Dachrahmen R | 0 | 0 | 4 | 60 | 0 | 0 | 4 | 50 |
| Heckklappe Oben | 2 | 80 | 0 | 0 | 3 | 50 | 5 | 20 |
| Heckklappe Unten | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Seitenwand HL | 19 | 70 | 12 | 20 | 17 | 50 | 5 | 30 |
| Seitenwand HR | 13 | 50 | 5 | 30 | 10 | 40 | 5 | 30 |
| Dellensumme | 310 | | 241 | | 236 | | 114 | |

Auf "diesem PC" gespeichert

Detailergebnisse HaSt


| | Hyundai I20 (silber) | | Volvo XC40 (grau) | | BMW 3er (weiß) | | BMW 5er (blau) | |
|--------------------|----------------------|----|-------------------|----|----------------|----|----------------|----|
| | Anzahl | Ø | Anzahl | Ø | Anzahl | Ø | Anzahl | Ø |
| Motorhaube | 48 | 40 | 94 | 20 | 39 | 20 | 31 | 30 |
| Kotflügel VL | 6 | 40 | 14 | 30 | 4 | 20 | 8 | 30 |
| Kotflügel VR | 10 | 30 | 3 | 20 | 3 | 40 | 3 | 30 |
| Tür VL | 2 | 40 | 4 | 20 | 6 | 30 | 5 | 20 |
| Tür VR | 11 | 30 | 1 | 10 | 6 | 30 | 2 | 10 |
| Tür HL | 2 | 30 | 13 | 20 | 6 | 20 | 1 | 20 |
| Tür HR | 16 | 30 | 2 | 30 | 7 | 20 | 3 | 30 |
| Dach | 139 | 40 | 146 | 30 | 131 | 30 | 0 | 0 |
| Dachrahmen L | 7 | 30 | 10 | 30 | 20 | 30 | 11 | 30 |
| Dachrahmen R | 11 | 30 | 8 | 30 | 8 | 30 | 13 | 20 |
| Heckklappe Oben | 1 | 20 | 0 | 0 | 1 | 20 | 0 | 0 |
| Heckklappe Unten | 5 | 30 | 2 | 40 | 4 | 20 | 8 | 20 |
| Seitenwand HL | 9 | 40 | 20 | 20 | 20 | 20 | 2 | 20 |
| Seitenwand HR | 2 | 30 | 9 | 20 | 11 | 30 | 1 | 20 |
| Dellensumme | 269 | | 326 | | 266 | | 88 | |

Detailergebnisse NTA


| | Hyundai I20 (silber) | | Volvo XC40 (grau) | | BMW 3er (weiß) | | BMW 5er (blau) | |
|--------------------|----------------------|----|-------------------|----|----------------|----|----------------|----|
| | Anzahl | Ø | Anzahl | Ø | Anzahl | Ø | Anzahl | Ø |
| Motorhaube | 69 | 30 | 88 | 20 | 22 | 20 | 36 | 30 |
| Kotflügel VL | 15 | 30 | 7 | 40 | 7 | 20 | 9 | 20 |
| Kotflügel VR | 13 | 20 | 3 | 20 | 4 | 30 | 1 | 20 |
| Tür VL | 6 | 40 | 1 | 30 | 7 | 30 | 4 | 30 |
| Tür VR | 10 | 50 | 2 | 20 | 5 | 40 | 1 | 40 |
| Tür HL | 3 | 60 | 12 | 30 | 3 | 30 | 2 | 20 |
| Tür HR | 13 | 40 | 2 | 40 | 3 | 30 | 6 | 30 |
| Dach | 94 | 40 | 121 | 20 | 120 | 30 | 2 | 20 |
| Dachrahmen L | 10 | 40 | 11 | 30 | 20 | 30 | 12 | 20 |
| Dachrahmen R | 12 | 50 | 5 | 30 | 14 | 30 | 10 | 30 |
| Heckklappe Oben | 2 | 60 | 2 | 30 | 0 | 0 | 4 | 20 |
| Heckklappe Unten | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Seitenwand HL | 16 | 40 | 13 | 20 | 17 | 20 | 2 | 30 |
| Seitenwand HR | 7 | 40 | 3 | 20 | 8 | 30 | 4 | 20 |
| Dellensumme | 270 | | 270 | | 230 | | 93 | |